



Florida Department of Environmental Protection

Bob Martinez Center 2600 Blair Stone Road Tallahassee, Florida 32399-2400 Charlie Crist Governor

Jeff Kottkamp Lt. Governor

Michael W. Sole Secretary

June 24, 2010

Mr. Dana Hayworth, P.G.
Department of the Navy
Naval Facilities Engineering Command Southeast
Building 135, Ajax Street
Naval Air Station Jacksonville
Jacksonville, Florida, 32212-0030

Re: Petroleum Product Recovery Program January 2009 to January 2010, Trumbo Point Tank Farm-Navy, Naval Air Station Key West, Florida

Dear Mr. Hayworth:

The Department has completed the technical review of the above referenced document dated April, 2010 (received June 24, 2010 via email) and the document is adequate for its intent. A copy of comments on the "Petroleum Product Recovery Program Interim Remedial Actions at Trumbo Point Tank Farm" has been included for your information. If I can be of any further assistance with this matter, please contact me at (850) 245-8998.

Sincerely

Tracie Lynn Bolanos

Remedial Project Manager Federal Programs Section

Dracie J. Bolano

Bureau of Waste Cleanup

JJCW ESN ESN

cc: Mr. Robert Courtright, Naval Air Station Key West, Key West, Florida

Ms. Amy Twitty, CH2M Hill, Navarre Beach, Florida

enclosure



Florida Department of Environmental Protection

Bob Martinez Center 2600 Blair Stone Road Tallahassee, Florida 32399-2400 Charlie Crist Governor

Jeff Kottkamp Lt. Governor

Michael W. Sole Secretary

March 1, 2010

Mr. Dana Hayworth, P.G.
Department of the Navy
Naval Facilities Engineering Command Southeast
Building 135, Ajax Street
Naval Air Station Jacksonville
Jacksonville, Florida 32212-0030

Re: Petroleum Product Recovery Program Interim Remedial Actions at Trumbo Point Tank Farm-Navy, Naval Air Station Key West, Florida

Dear Mr. Hayworth:

The Department has completed the technical review of the above referenced document dated October 26, 2009 (received January 28, 2010 via the partnering meeting) and has the following general comments:

- 1. The Department concurs with the soil excavation and de-watering activities that took place in the Trumbo Point Tank Farm (TPTF) south area activities explained in this document.
- 2. The Department concurs with the first two recommendations listed on page 15 of this document which will begin to address data gaps that presently exist at this site.
- 3. The Department does not concur with the third recommendation which states, "The Petroleum Product Recovery Program (PPRP) should be amended to include a Monitoring Only Plan to perform product gauging and groundwater sampling in select wells at the site." We will need to review the new data that will be generated before we can consider this approach.

If I can be of any further assistance with this matter, please contact me at (850) 245-8998.

Sincerely

Tracie Lynn Bolanos Remedial Project Manager

Federal Programs Section

Bureau of Waste Cleanup

cc: Mr. Robert Courtright, Naval Air Station Key West, Key West, Florida

Ms. Amy Twitty, CH2M Hill, Navarre Beach, Florida

Fracis L. Bolanos

Mr. Chuck Bryan, Tetra Tech Aiken, South Carolina

ALJIC ESKESN